



MSA	Models	Hole sizes (carats)	Size mm	Kg
40.003	3 arms	0.01 to 4.00	75 x 16 x 3	0.026
40.004	4 arms	0.01 to 6.00	75 x 16 x 3.5	0.030
40.005	5 arms	0.01 to 8.00	76 x 18 x 4	0.038
40.006	6 arms	0.01 to 12.00	87 x 20 x 5	0.060
40.007	7 arms	0.01 to 15.00	87 x 20 x 6	0.066
40.008	8 arms	0.01 to 20.00	87 x 25 x 6.5	0.090

Nickel silver gauge for stones.

➤ See chapter PERF.



MSA	Number of plates	Plates ø mm	Holes numbers	Kg
40.120	23	32	000, 00, 0, 1, 2, 3, 4 ... 20	0.150
40.121	42	32	000, 00, 0, 1, 1.5, 2, 2.5, 3 ... 20	0.450
40.122	23	47	000, 00, 0, 1, 2, 3, 4 ... 20	0.300
40.123	42	47	000, 00, 0, 1, 1.5, 2, 2.5, 3 ... 20	0.475
40.124	23	66	000, 00, 0, 1, 2, 3, 4 ... 20	0.460
40.125	42	66	000, 00, 0, 1, 1.5, 2, 2.5, 3 ... 20	0.850
40.126	23	80	000, 00, 0, 1, 2, 3, 4 ... 20	0.800
40.127	42	80	000, 00, 0, 1, 1.5, 2, 2.5, 3 ... 20	1.400
40.128	42	107	000, 00, 0, 1, 1.5, 2, 2.5, 3 ... 20	3.000

Sieve for stones and pearls in a metal container.



MSA	Size mm	Kg
40.200	ø 35.50 x 30	0.032

Tool for holding pearls during drilling.